

EGNOS SERVICE NOTICE

Number: 017

Revision: 1.1

To: EDAS Users
Date: 19/03/2018
Subject: EDAS FTP RINEX navigation files

EDAS FTP RINEX navigation files dated after 27th January 2017 were detected to sporadically contain GPS satellite ephemeris linked to an incorrect PRN number. As announced in v1.0 of this service notice, a solution has been developed and integrated into an EDAS system release.

Hence, this service notice informs users that the sporadic problem of incorrect GPS ephemeris in EDAS FTP RINEX navigation files is solved and it will no longer be observed in files dated after March 7th 2018.

Users are invited to contact the EGNOS Helpdesk if abnormal performance results are observed while working with EDAS FTP RINEX navigation files.

CONTACT US

Should you have any question related to this Service Notice or EGNOS, please, contact egnos-helpdesk@essp-sas.eu or +34 911 236 555 (H24/7)

For more information about EGNOS, please, visit the EGNOS User Support website at <https://egnos-user-support.essp-sas.eu>